पहिष्य विद्या मन्दिर (सीनियर सेकेण्डी स्वाल नावीन) पताः ग्राम बुठार, डाकघर भरमीटी, नहरू नावीन, जिला हमीरपुर (हिल्प्रूट)



Affiliated to CBSE. Affiliation No. 630096 MAHARISHI VIDYA MANDIR

(Senior Secondary School Nadaun)
Address:- Vill Kuther, P.O. Bharmoti
Teh, Nadaun Distt. Hamirpur (H.P.)177033
Phone No. 01972-233779: 9485-14-37-2009
E-mail: mymeadaun/2007@yahco-co-iu

Fax: 01972-233709, 780 15-86 104 [Cmare: mumnadoun & marmale 1;]

Ref. No /MVM/NDN/2020-21/42

Jal Guru Dev

David C4 (00 2001

The Executive Engineer
Hamirpur Division
HP PWD Hamirpur

Sub: Renewal of Building Safety Certificate for Affiliation Renewal 2020-21

Respected Sir

As per the guidelines received from the office of Dy. Director Elementary Education Hamirpur, our school is in need of Building Safety Certificate for renewal of affiliation

You are requested to renew the building safety Certificate of our school. Previous year certificate and building map are attached herewith.

Hope for your kind consideration

Regards

Principal

Principal
M.V.M. Sr. Sec. Public School
Nadaun

Distt. Hamirpur (H.P.)-177033

UNDER PROCESS

Himachal Pradesh Dated:- 17-1-19 No. PWH/HMR/CB/WA-I/B-4 Building Safety/2019-20/-/22-03-4 Maharishi Vidhya Mandir, S.S. Public School Nadaun, Tehsil Nadaun Distt. Hamirpur (H.P) Subject:-Building safety Certificate. Kindly find enclosed herewith the building safety certificate in respect of building of the Maharishi Vidhya Mandir School S.S. Public School Nadaun Tehsil Nadaun Distt .Hamirpur (H.P) for the year 2019-2020.

DA: As above

Executive Engineer, Hamirpur Division, HP PWD, Hamirpur

Copy forwarded to the Assistant Engineer Nadaun HPPWD Sub

Division Nadaun for information with reference to his letter No. 998 dated 11-9-2019.

DA: Nil.

Executive Engineer, Hamirpur Division, HP PWD, Hamirpur.

M.V.M. Sr. Sec. Wub

Nadaun

Distt. Happirpur (H.P.)

BUILDING CERTIFICATE

The School building of Maharishi Vidya Mandir S.S.Public School Nadaun, Tehsil Nadaun. Distt Hamirpur (H.P) was inspected by the concerned Junior Engineer on dated 3-9-2019. The building has neither been designed nor constructed by the this department. No earthquake resistant norms have been adopted by the competent adopted for this building. No structural drawings approved by the competent Government Agency have been produced. The structure is a Non Engineering structure. Hence the structural safety of this building can not be ensured specially from earthquake point of view. The year of construction of this building is also not known. This department will not be responsible for any type of loss of life and property etc. if this structure fails under any circumstances. However as per visual inspection, the building appears to be safe at present only. This certificate is valid for academic session 2019-2020.

Junior Engineer, Section Madely Assistant Engineer, Sub-Division, HP.PWD Nadaun

M.V.M. Sr. Sec. Public School

Nadaun

Distt. Hamirpur (H.P.)-177033

Executive Engineer Hamirpur Division (B&R)

H.P.P.W.D. Hamirpur